

END OF REPAIRS

May 2021

END OF REPAIR NOTIFICATION MOTOTRBO™ Digital Portable and Mobile Radios

END OF REPAIRS NOTIFICATION FOR FOLLOWING MOTOTRBO™ PORTABLE AND MOBILE RADIOS

This is information that Motorola Solutions EMEA Repair will stop repairs from 30th May 2021 for following MOTOTRBO™ Digital Portable Radios models cancelled in October 2016:

MODELS AFFECTED

DP2400 and DP2600 series Digital Portable Radios

MODEL (PRODUCT No)	DESCRIPTION
MDH02JDH9JA2AN	DP2600 136-174 5W LKP PAN302F
MDH02JDC9JA2AN	DP2400 136-174 5W NKP PAN302C
MDH02RDH9JA2AN	DP2600 403-527 4W LKP PAN502F
MDH02RDC9JA2AN	DP2400 403-527 4W NKP PAN502C
MDH02NDC9JA2AN	DP2400 350-400M 4W NKP PAN802C
MDH02KDC9JA2AN	DP2400 300-360M 4W NKP PAN402C
MDH02JDH9JA2ANB	DP2600 136-174 5W LKP PAN302F
MDH02JDC9JA2ANB	DP2400 136-174 5W NKP PAN302C
MDH02RDH9JA2ANB	DP2600 403-527 4W LKP PAN502F
MDH02RDC9JA2ANB	DP2400 403-527 4W NKP PAN502C
MDH02NDC9JA2ANB	DP2400 350-400M 4W NKP PAN802C
MDH02KDC9JA2ANB	DP2400 300-360M 4W NKP PAN402C

DP3441 series Digital Portable Radios

MODEL (PRODUCT No)	DESCRIPTION
MDH69JDC9KA2AN	DP3441 136-174M 5W NKP GPS BT PRE302BE
MDH69JDC9KA2ANB	DP3441 136-174M 5W NKP GPS BT PRE302BE
MDH69RDC9KA2AN	DP3441 403-527M 4W NKP GPS BT PRE502BE
MDH69RDC9KA2ANB	DP3441 403-527M 4W NKP GPS BT PRE502BE

Motorola Solutions Confidential - Do Not Redistribute - PartnerEmpower Member, Customer, and Prospective Customer Use Only

Whilst care has been taken to ensure the accuracy of the information contained in this bulletin, Motorola Solutions retains the right to make changes at any time without notice. Motorola and the Stylized M Logo are trademarks or registered trademarks of Motorola Trademark Holdings, LLC and are used under license. All other trademarks are the property of their respective owners. © 2021 Motorola Solutions, Inc. All rights reserved.



END OF REPAIRS

May 2021

END OF REPAIR NOTIFICATION MOTOTRBO™ Digital Portable and Mobile Radios

DP4400, DP4401, DP4600, DP4601, DP4800, DP4801 series Digital Portable Radios

MODEL (PRODUCT No)	DESCRIPTION
MDH56JDN9KA1AN	DP4801 136-174 5W FK GPSBT PBE302HE
MDH56JDN9JA1AN	DP4800 136-174 5W FK PBE302H
MDH56JDH9KA1AN	DP4601 136-174 5W LK GPSBT PBE302FE
MDH56JDH9JA1AN	DP4600 136-174 5W LK PBE302F
MDH56JDC9KA1AN	DP4401 136-174 5W NK GPSBT PBE302CE
MDH56JDC9JA1AN	DP4400 136-174 5W NKPBE302C
MDH56JDN9KA2AN	DP4801 136-174 5W FKGLONASS BT PBE302HE
MDH56JDC9KA2AN	DP4401 136-174 5W NK GLONASS BT PBE302CE
MDH56RDN9KA1AN	DP4801 403-527 4W FK GPSBT PBE502HE
MDH56RDN9JA1AN	DP4800 403-527 4W FK PBE502H
MDH56RDH9KA1AN	DP4601 403-527 4W LK GPSBT PBE502FE
MDH56RDH9JA1AN	DP4600 403-527 4W LK PBE502F
MDH56RDC9KA1AN	DP4401 403-527 4W NK GPSBT PBE502CE
MDH56RDC9JA1AN	DP4400 403-527 4W NK PBE502C
MDH56KDC9KA1AN	DP4401 300-360M 4W NKP GPS BT PBE402CE
MDH56NDC9KA1AN	DP4401 350-400M 4W NKP GPS BT PBE802CE
MDH56KDN9KA1AN	DP4801 300-360M 4W FKP GPS BT PBE402HE
MDH56NDN9KA1AN	DP4801 350-400M 4W FKP GPS BT PBE802HE
MDH56RDN9KA2AN	DP4801 403-527 4W FK GLONASS BT PBE502HE
MDH56RDC9KA2AN	DP4401 403-527 4W NKGLONASS BT PBE502CE
MDH56JDN9KA1ANB	DP4801 136-174 5W FK GPSBT PBE302HE
MDH56JDN9JA1ANB	DP4800 136-174 5W FK PBE302H
MDH56JDH9KA1ANB	DP4601 136-174 5W LK GPSBT PBE302FE
MDH56JDH9JA1ANB	DP4600 136-174 5W LKPBE302F
MDH56JDC9KA1ANB	DP4401 136-174 5W NK GPSBT PBE302CE
MDH56JDC9JA1ANB	DP4400 136-174 5W NK PBE302C
MDH56JDN9KA2ANB	DP4801 136-174 5W FK GLONASS BT PBE302HE
MDH56JDC9KA2ANB	DP4401 136-174 5W NK GLONASS BT PBE302CE
MDH56RDN9KA1ANB	DP4801 403-527 4W FK GPSBT PBE502HE
MDH56RDN9JA1ANB	DP4800 403-527 4W FK PBE502H

END OF REPAIRS

May 2021

END OF REPAIR NOTIFICATION MOTOTRBO™ Digital Portable and Mobile Radios

MDH56RDH9KA1ANB	DP4601 403-527 4W LK GPSBT PBE502FE
MDH56RDH9JA1ANB	DP4600 403-527 4W LK PBE502F
MDH56RDC9KA1ANB	DP4401 403-527 4W NK GPSBT PBE502CE
MDH56RDC9JA1ANB	DP4400 403-527 4W NK PBE502C
MDH56KDC9KA1ANB	DP4401 300-360M 4W NKPGPS BT PBE402CE
MDH56NDC9KA1ANB	DP4401 350-400M 4W NKPGPS BT PBE802CE
MDH56KDN9KA1ANB	DP4801 300-360M 4W FKPGPS BT PBE402HE
MDH56NDN9KA1ANB	DP4801 350-400M 4W FKPGPS BT PBE802HE
MDH56RDN9KA2ANB	DP4801 403-527 4W FKGLONASS BT PBE502HE
MDH56RDC9KA2ANB	DP4401 403-527 4W NKGLONASS BT PBE502CE

SL4000, SL4010 series Digital Portable Radios

MODEL (PRODUCT No)	DESCRIPTION
MDH81QCN9MA2AN	SL4000 403-470M 2W EN FKPPMT532HE
MDH81QCN9NA2AN	SL4010 403-470M 2W EN GOBPMT532HEG
MDH81QCN9MA2ANB	SL4000 403-470M FKP Bulk PMT532HE
MDH81QCN9NA2ANB	SL4010 403-470M GOB Bulk PMT532HEG

DM4400, DM4401, DM4600, DM4601 series Digital Mobile Radios

MODEL (PRODUCT No)	DESCRIPTION
MDM28QNC9JA2AN	DM4400 403-470 LP ND MBA504D
MDM28QNC9KA2AN	DM4401 403-470 LP GPSBT ND MBA504DE
MDM28QNN9JA2AN	DM4600 403-470 LP CD MBA504N
MDM28QNN9KA2AN	DM4601 403-470 LP GPSBT CD MBA504NE
MDM28QPC9JA2AN	DM4400 403-470 HP ND MBA507D
MDM28QPC9KA2AN	DM4401 403-470 HP GPSBT ND MBA507DE
MDM28QPN9JA2AN	DM4600 403-470 HP CD MBA507N
MDM28QPN9KA2AN	DM4601 403-470 HP GPSBT CD MBA507NE
MDM28KRN9KA2AN	DM4601 300-360M LP-HP BT/GLONASS CD MBA408NE

END OF REPAIRS

May 2021

END OF REPAIR NOTIFICATION MOTOTRBO™ Digital Portable and Mobile Radios

MDM28KRC9KA2AN	DM4401 300-360M LP-HP BT/GLONASS ND MBA408DE
MDM28PRN9KA2AN	DM4601 350-400M LP-HP GPSBT CD MBA808NE
MDM28PRC9KA2AN	DM4401 350-400M LP-HP GPSBT ND MBA808DE
MDM28JNC9JA2AN	DM4400 136-174 LP ND MBA304D
MDM28JNC9KA2AN	DM4401 136-174 LP GPSBT ND MBA304DE
MDM28JNN9JA2AN	DM4600 136-174 LP CD MBA304N
MDM28JNN9KA2AN	DM4601 136-174 LP GPSBT CD MBA304NE
MDM28JQC9JA2AN	DM4400 136-174 HP ND MBA307D
MDM28JQC9KA2AN	DM4401 136-174 HP GPSBT ND MBA307DE
MDM28JQN9JA2AN	DM4600 136-174 HP CD MBA307N
MDM28JQN9KA2AN	DM4601 136-174 HP GPSBT CD MBA307NE
MDM28QNC9JA2ANB	DM4400 403-470 LP ND MBA504D
MDM28QNC9KA2ANB	DM4401 403-470 LP GPSBT ND MBA504DE
MDM28QNN9JA2ANB	DM4600 403-470 LP CD MBA504N
MDM28QNN9KA2ANB	DM4601 403-470 LP GPSBT CD MBA504NE
MDM28QPC9JA2ANB	DM4400 403-470 HP ND MBA507D
MDM28QPC9KA2ANB	DM4401 403-470 HP GPSBT ND MBA507DE
MDM28QPN9JA2ANB	DM4600 403-470 HP CD MBA507N
MDM28QPN9KA2ANB	DM4601 403-470 HP GPSBT CD MBA507NE
MDM28KRN9KA2ANB	DM4601 300-360M LP-HP BT/GLONASS CD MBA408NE
MDM28KRC9KA2ANB	DM4401 300-360M LP-HP BT/GLONASS ND MBA408DE
MDM28PRN9KA2ANB	DM4601 350-400M LP-HP GPSBT CD MBA808NE
MDM28PRC9KA2ANB	DM4401 350-400M LP-HP GPSBT ND MBA808DE
MDM28TRC9JA2ANB	DM4400 450-527 LP-HP GOB ND MBA608D
MDM28TRC9KA2ANB	DM4401 450-527 LP-HP GOB BT/GPS ND MBA608DE
MDM28TRN9JA2ANB	DM4600 450-527 LP-HP GOB CD MBA608N
MDM28TRN9KA2ANB	DM4601 450-527 LP-HP GOB BT/GPS CD MBA608NE
MDM28JNC9JA2ANB	DM4400 136-174 LP ND MBA304D
MDM28JNC9KA2ANB	DM4401 136-174 LP GPSBT ND MBA304DE
MDM28JNN9JA2ANB	DM4600 136-174 LP CD MBA304N
MDM28JNN9KA2ANB	DM4601 136-174 LP GPSBT CD MBA304NE

END OF REPAIRS

May 2021

END OF REPAIR NOTIFICATION MOTOTRBO™ Digital Portable and Mobile Radios

MDM28JQC9JA2ANB	DM4400 136-174 HP ND MBA307D
MDM28JQC9KA2ANB	DM4401 136-174 HP GPSBT ND MBA307DE
MDM28JQN9JA2ANB	DM4600 136-174 HP CD MBA307N
MDM28JQN9KA2ANB	DM4601 136-174 HP GPSBT CD MBA307NE

CONTACTS AND CUSTOMER INFORMATION

Please contact the European Repair Services Centre for further information.

Austria (German): 0800 281 195

Denmark (English): 80 253 546

France (French): 0800 914 532 or +33 176 775 609

Germany (German): 0800 724 6872 or +49 692 222 1568

Italy (Italian): 800 791 276

Netherlands (English): 0800 0249 893

Norway (English): 800 14 802

Poland (Polish): 00800 1215 772

Spain (Spanish): 9009 416 84

United Kingdom (English): 0800 731 3496 or +44 207 019 0461

Email Contact:

repair.emea@motorolasolutions.com